



$$R_t = R_0 (1 + C_1 \times t + C_2 \times t^2) \text{ for } t > 0 \text{ } ^\circ\text{C}$$

$$R_t = R_0 (1 + C_1 \times t + C_2 \times t^2 + C_3 \times t - 100 t^3) \text{ for } t < 0 \text{ } ^\circ\text{C}$$

		-	-

